PAGE: 1

PRINT DATE: 03/30/90

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE

NUMBER: 03-3-2002-X

SUBSYSTEM NAME: ORBITAL MANEUVERING SYSTEM (OMS)

REVISION: 2 03/16/90

PART NAME VENDOR NAME

PART NUMBER VENDOR NUMBER

LRU O1

TANK, PROPELLANT STORAGE, OX.

73P550013

MDAC/AMCO

LRU 02

TANK, PROPELLANT STORAGE, FUEL 73A740000

MDAC/AMCO

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS: TANK, OMS PROPELLANT STORAGE, MMH, N204, MONOLITHIC TITANIUM (6AL4V).

QUANTITY OF LIKE ITEMS: 4 TWO PER POD

FUNCTION:

STORES PROPELLANT AT AN ULLAGE PRESSURE OF 250-313 PSI. REGULATED HELIUM IS SUPPLIED TO THE ULLAGE TO FORCE PROPELLANT TO THE OMS ENGINE OR RCS ENGINE AS REQUIRED. THE TANK ALSO HOUSES ZERD G PROPELLANT ACQUISITION, RETENTION & SCREEN DEVICES IN ADDITION TO PROPELLANT GAUGING DEVICES. THE TANK IS A CYLINDER WITH ELLIPTICAL DOMES AND IS 49 INCHES IN DIAMETER WITH A VOLUME OF 90 FT3. SIX DOORS ARE PROVIDED IN THE TANK FOR ACCESS AND FEEDTHROUGH.

PAGE: 6 PRINT DATE: 03/30/90 FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE NUMBER: 03-3-2002-02 REVISION# 2 03/16/90 SUBSYSTEM: ORBITAL MANEUVERING SYSTEM (OMS) LRUTANK, PROPELLANT STORAGE, FUEL ITEM NAME: TANK, PROPELLANT STORAGE, OX. FAILURE MODE:1R2 CRITICALITY OF THIS FAILURE MODE: EXTERNAL LEAKAGE (FLANGE SEAL LEAKAGE) MISSION PHASE: PL PRELAUNCH LQ. LIFT-OFF 00 ON-ORBIT DO DE-ORBIT LS LANDING SAFING VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA : 103 DISCOVERY : 104 ATLANTIS CAUSE: DAMAGE TO ACCESS DOOR OR SEAL LANDS, MATERIAL DEFICIENCY OR INCORRECT SEAL, SHOCK, VIBRATION, PROPELLANT EXPOSURE, LONG TERM MOLECULAR TYPE LEAKAGE (SEAL PERMEATION). CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO REDUNDANCY SCREEN A) PASS B) FAIL C) PASS PASS/FAIL RATIONALE: A) B) C) - FAILURE EFFECTS ~ (A) SUBSYSTEM: NO EFFECT UNLESS REDUNDANT SEALS LEAK.

(B) INTERFACING SUBSYSTEM(S):

NO EFFECT - POSSIBLE CORROSION/MATERIAL DAMAGE TO ADJACENT

PAGE: 7

PRINT DATE: 03/30/90

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: 03-3-2002-02

STRUCTURE/TPS/ELECTRICAL INSULATION/EPOXY MATERIALS IF REDUNDANT SEALS LEAK.

- (C) MISSION:
- NO EFFECT LEAKAGE OF REDUNDANT SEALS WOULD RESULT IN LAUNCH DELAY.
- (D) CREW, VEHICLE, AND ELEMENT(S):
 NO EFFECT UNLESS REDUNDANT SEALS FAIL.
- (E) FUNCTIONAL CRITICALITY EFFECTS:
 POSSIBLE CREW/VEHICLE LOSS IF LEAK RESULTS IN EXCESSIVE LOSS OF
 PROPELLANT OR PRESSURANT. IR EFFECT REQUIRES FAILURE OF REDUNDANT
 SEALS. NO INSTRUMENTATION AVAILABLE FOR DETECTION OF FIRST FAILURE IN
 FLIGHT.

- DISPOSITION RATIONALE -

(A) DESIGN:

THE FACTOR OF SAFETY (BURST) IS 1.5 X WORKING PRESSURE. COMPLETE STRESS ANALYSIS FOR EACH TANK SEGMENT WAS PERFORMED. PROPELLANT COMPATIBLE MATERIALS ARE UTILIZED. TANK IS CLASSIFIED AS FRACTURE CRITICAL FOR HANDLING & IS SUBJECT TO FRACTURE CONTROL REQUIREMENTS. ALL FITTINGS AND ACCESS DOORS USED ON THE TANK HAVE REDUNDANT STATIC AND SPRING LOADED SEALS. DOOR SEALS ARE VERIFIABLE.

■ (8) TEST:

QUALIFICATION TESTS

600 PRESSURE CYCLES, 90-DAY CREEP AND PROPELLANT EXPOSURE TEST, RANDOM VIBRATION. ALSO QUALIFIED AS PART OF POD ASSEMBLY. VIBRO ACOUSTIC TESTING AT JSC - 100 EQUIVALENT MISSIONS. HOT FIRE TEST PROGRAM AT WSTF-517 TESTS. APPROX 7 YEARS PROPELLANT EXPOSURE.

ACCEPTANCE TEST

PROOF PRESSURE AND LEAKAGE, RADIOGRAPHIC AND X-RAY TESTS TO VERIFY NO PERMANENT DEFORMATION OR FLAW GROWTH, WELD INSPECTION FOR EVIDENCE OF STRESS RISER OR OTHER FLAMS.

GROUND TURNAROUND

V43CBO.210 PERFORMS FIRST FLIGHT EXTERNAL LEAK CHECKS.

V43CBO.215 REQUIRES PERIODIC LEAK CHECK OF FLANGE SEALS EVERY 5th FLIGHT.

V43CBO.230 TOXIC VAPOR LEAK CHECK ON PROPELLANT TANK FOR FIRST FLIGHT AND ON A CONTINGENCY BASIS.

V43CEO.O30 PERFORMS SUBSYSTEM INSPECTION EVERY 5TH FLIGHT.V43CEO.130 REQUIRES POD PURGE WHEN POD IS OFF ORBITER.

PAGE: 8 PRINT DATE: 03/30/90

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: 03-3-2002-02

V43CEO.120 REQUIRES SAMPLING OF STATIC AIR IN VARIOUS POD INTERNAL COMPARTMENTS FOR DETECTION OF MINOR PROPELLANT LEAKAGE. THE SECOND FLIGHT AND EVERY FLIGHT THEREAFTER.

WHEN POD IS INSTALLED ON ORBITER POD PURGE REQUIREMENTS ARE DEFINED IN VOSAGO.010 (OLF), VOSAGO.020 (GPF), VOSAGO.030 (VAB), AND VOSAGO.040(PAD).

PROPELLANT TANK PRESSURE AND TEMPERATURE MONITORED EACH FLIGHT FOR EVIDENCE OF LEAKAGE.

(C) INSPECTION:

RECEIVING INSPECTION MATERIALS AND PROCESSES CERTIFICATION ARE VERIFIED BY INSPECTION.

CONTAMINATION CONTROL CLEANLINESS TO LEVEL 200 FOR MMH AND 200A FOR NTO AND CORROSION PROTECTION PROVISIONS ARE VERIFIED BY INSPECTION

ASSEMBLY/INSTALLATION
MANUFACTURING ASSEMBLY AND INSTALLATION PROCEDURES ARE VERIFIED BY
INSPECTION. CRITICAL DIMENSIONS AND SURFACE FINISHES ARE VERIFIED BY
INSPECTION. DIMENSIONAL AND VISUAL INSPECTION OF COMPONENTS DURING
FABRICATION ARE VERIFIED BY INSPECTION.

NUNDESTRUCTIVE EVALUATION PENETRANT AND RADIOGRAPHIC INSPECTION OF WELDS ARE VERIFIED BY INSPECTION.

CRITICAL PROCESSES
FORGING MATERIAL GRAIN STRUCTURE IS VERIFIED BY INSPECTION. WELDING
PROCESS AND VERIFICATION THAT WELDS MEET SPECIFICATION REQUIREMENTS ARE
VERIFIED BY INSPECTION.

TESTING
TEST EQUIPMENT AND TOOL CALIBRATION ARE VERIFIED BY INSPECTION.
ACCEPTANCE TEST IS VERIFIED BY INSPECTION.

HANDLING/PACKAGING
HANDLING, PACKAGING, STORAGE AND SHIPPING REQUIREMENTS ARE VERIFIED BY INSPECTION.

(O) FAILURE HISTORY: CAR'S AD1528 AND AD1622 RECORD EVIDENCE OF FLANGE SEAL LEAKAGE. THE LEAKAGE IS EVIDENCED BY CORROSION ON SURROUNDING COMPONENTS AND

--- ^ 25 52

PRINT DATE: 03/30/90

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE NUMBER: 03-3-2002-02

SHIELDED ELECTRICAL WIRES. THE LEAKAGE IS MINOR AND MAY NOT BE DETECTED BY THE HELIUM LEAK TESTS, POSSIBLY DUE TO SWELLING OF THE SEALS. THE LEAKAGE IS DUE TO TEFLON SEAL PERMEATION. EXAMINATION HAS REVEALED NO DAMAGE TO THE FLANGE. ADDITIONAL LEAK CHECKS (STATIC PERIOD FOLLOWED BY PURGE AND VAPOR DETECTION TEST) ARE PERFORMED FIRST FLIGHT AND EVERY 5th FLIGHT. PERIODIC INSPECTION AND CONSTANT PURGE OF THE POD ARE CONDUCTED DURING PRELAUNCH AND TEST PERIODS.

(E) OPERATIONAL USE:

FLANGE SEAL LEAKAGE IS UNLIKELY TO CAUSE MAJOR PROPELLANT LOSS. THE PRIMARY CONCERN IS CORROSION WITHIN POD DUE TO PROPELLANT EXPOSURE. CREW ACTION IS REQUIRED FOR THESE CASES. THE FOLLOWING ACTIONS ARE TAKEN IF LEAKAGE IS SIGNIFICANT. USE PERIGEE ADJUST BURN TO DEPLETE PROPELLANT FROM LEAKING POD AND REDUCE DELTA V REQUIREMENTS FOR DEORBIT. AFTER LEAKED PROPELLANT HAS DISPERSED, PERFORM DEORBIT BURN WITH GOOD POD.

- APPROVALS -

RELIABILITY ENGINEERING: J. N. HART

DESIGN ENGINEERING : D. W. CARLSON

QUALITY ENGINEERING : W. J. SMITH NASA RELIABILITY :

MASA SUBSYSTEM MANAGER:

MASA QUALITY ASSURANCE :